



21.21.00011

12-NOV-2013

Ref:

Date:

First Tssue

Cabin Air Quality Troubleshooting Advice

ATA: 21-21 FIN: A300 A/C Type: A/C Serie: Topic: A300-600 A310 A318 A319 A320 A321 A330 A340 A340-500 A340-600 A350 A380 Part Number:

Last Publication 10-JUL-2017
Date:

Supplier: Linked

Linked

Articles:

Documentation:

Old Wise Ref:

EngOps-16325

■Engineering Support

Model: Manufacturer: First Issue Date: Last Publication Date: 12-NOV-2013 10-JUL-2017

Applicability

ALL

References

THIS ARTICLE REPLACES SIL 21-132

Now EngOps-16326 Dry Ice Transportation

Now EngOps-16316 Environmental Control System Decontamination Procedure

Now EngOps-16317 Aircraft Cabin Air Quality

FAST 19

Cabin Air Quality Article

FCOM 02.02.13

Inclement Weather Operation (A300-600/A310)

FCOM PROC/SUP PROC/COLD WEATHER PROC Cold Weather Procedures (A380)

Description

Continuing interest in the subject of cabin air quality has prompted this WISE article which aims to consolidate the information and advice already contained in other sources.

This WISE Article highlights best practice available for troubleshooting with an overview of fleet experience and also provides recommendations after a cabin air quality event.

BACKGROUND:

All Airbus aircraft are tested to confirm that airflow rate and contamination levels are good compared to the relevant airworthiness regulations, and in respect of contaminants against internationally accepted safety guidelines, see the following documents;

Now EngOps-16317 Aircraft Cabin Air Quality

FAST 19 Cabin Air Quality Article

This WISE article provides helpful data based on operator experience, and troubleshooting best practice

Solution

Possible Sources Affecting Cabin Air Quality

There are many potential causes of cabin odours or smoke and it can sometimes prove difficult to isolate the cause of an odour quickly. The following generic list (not ranked)covers the possible causes of odours that should be considered;

- Engine or APU Ingestion of
 - De-icing fluid into inlet (See precautions in FCOM 2.02.13 (A300-600/A310) or PRO-SUP-91-30 (A320 and A330/A340 family) or PROC/SUPP PROC/COLDWEATHERPROC (A380)
 - o Exhaust fumes from other aircraft, GPU etc
 - o Pollution (eg. smoke from fires)
 - o Hydraulic fluid leaks
 - o Birds
 - Compressor wash procedure residues
 - o Pollens
- Galley Equipment, ovens, coffee makers etc (Ref MPD tasks for galley and toilet air extraction systems)
- Damaged electrical wiring or components
- Inappropriate or excessive use of CO₂ (dry ice) by caterers or excessive quantities being transported (see EngOps-16326)
- Toilet fluid spillage, leakage and also unapproved mixing of different disinfectant fluids within the toilet.
- Leakage of the rain repellent system or rain repellent contamination within the cabin or flightdeck.
- Spillage's within cargo compartments
- Items stowed in overhead overhead bins
- APU oil leaks into the bleed system
- Engine oil leaks into the bleed system
- Contamination of the ECS

First Steps in Troubleshooting a Cabin Odour Report

Usually the source of a cabin odour report is easily determined by considering each of the potential causes above, but sometimes the cause is not obvious. In these cases the questionnaire in Attachment 2 can be used as a way of gathering the data necessary to progress troubleshooting which includes; Description of Odour, Location of Odour, Flight phase when Odour was reported, Bleed system selections etc.

In order to share fleet experience and optimise troubleshooting, the following tables rank the causes of cabin odour for the fleet based on;

- Table 1 Reported Odour Causes Ranked by Highest Number of Reports
- Table 2 Reported Odour Descriptions Correlated to Most Reported Odour Cause
- Table 3 Reported Location of Odours Correlated by Most Likely Odour Cause
- Table 4 Flight Phase When Odour Reported Correlated by Most Reported Odour Cause

These tables are based on available operator feedback and so represent a historical view. Therefore, some of the failure modes causing odour reports listed in the following tables have been rectified by modification action and may not be relevant to all or any existing aircraft standards.

Note: For A320 Family operators, attention is drawn to the TSM task 05-50-00-810-831-A which contains a decision table to identify odour sources, based on operator experience.

RCSM NOTE: Please use the questionnaire at attachment 2 to record data when appropriate, however even when the questionnaire is not used it is still useful to forward all cabin air quality reports and occurrences to SEEE4.

Table 1 - Reported Odour Causes Ranked by Highest Number of Reports Per Aircraft Type

Most Reported	A300	A300-600	A310		
Primary	Cause	Primary	Cause	Primary	Cause Breakdown
Cause	Breakdown	Cause	Breakdown	Cause	Cause Dieakdowii
Electrical Equipment	N2 Indicator Lav Flush Motor ADI BCL	r Electrical Equipment	TRU IFE CRT CB Panel	Electrical Equipment	TRU CB Panel ND
Galley Equipment	Oven Coffee Maker Water Heater	APU	Oil Leak	Galley Equipment	Wiring
Engine	Oil Leak	Galley Equipment		Hnanne	Hyd fluid ingestion
		Engine	Oil Leak		
Most Reported	A319	A320	A321		
Primary		Primary	Cause	Primary	Cause
Cause	Breakdown	Cause	Breakdown	Cause	Breakdown
APU	Oil Leak	APU	Oil Leak	APÜ	Oil Leak
Electrical Equipment	MCDH	Electrical Equipment	Ballast Unit TRU Reading Light Extract Fan	Electrical Equipmen	Heated Floor Panel RMP MCDU

Avionics

ELAC

Extract Fan

Light Bulb

Blower **MCDU GPCU**

Engine Oil Leak Engine Oil Leak Galley Coffee Maker Galley Coffee Maker

Equipment Hot Plate Equipment Oven

Most Reported A330 A340

Primary Primary Cause Breakdown

Cause Breakdown Cause Cause

IFE Lighting Controller

Electrical Light Electrical ACP Equipment **FCU** Equipment **Ballast Unit**

ECAM DMC2

Coffee Maker Galley Oven

Galley Equipment Oven Equipment Coffee Maker Clogged Filters

Prior Engine Wash

APU Oil Leak Engine Oil Leak

Table 2 – Reported Odour Descriptions Correlated to Most Reported Odour Cause

Description Primary Cause (Most Reported Listed First)

Electrical Equip / IFE

Acrid Engine Oil Leak

Electrical Equipment

Galley Equipment Burning

Ingestion of Bird

Contaminated bleed ducts

Chemical **APU Ingestion**

Leakage of rain repellent fluid

Smoke Hood

Chlorine Blocked Door area drain

Electrical **Electrical Equipment**

APU or Engine Oil Leaks, **Dirty Socks**

possibly contaminated ECS

Foul Toilet

APU FCU/Fuel line

Fuel

APU ingestion of engine exhaust

Oil Engine or APU Oil Leak

Skydrol Engine Hydraulic

Wiring

Sulphur Avionics filter water contamination

Light Bulb

<u>Table 3 – Reported Location of Odours Correlated by Most Reported Odour Cause</u>

Location Description	Primary Cause (Most Reported Listed First)					
A300/A310/A300- 600	A319/A320/A321	A330/A340				
Cabin	Electrical Equipment	APU Oil Leak Engine Oil Leak Electrical Equip Galley Equipment	Electrical Equipment APU Oil Leak Engine Oil Leak			
Cockpit	Electrical Equipment APU Oil Leak Engine Oil Leak Leakage of rain repellent fluid	Electrical Equipment Engine Oil Leak APU Oil Leak	Electrical Equipment APU Oil Leak			
Cabin & Cockpit	Engine, Hydraulic Fluid Ingest	Engine APU ECS	APU Ingestion			
Fwd Galley	Galley Equipment	Galley Equipment	Galley Equipment			
Aft Galley	Galley Equipment	Galley Equipment	Galley Equipment			

Table 4 – Flight Phase When Odour Reported Correlated by Most Reported Odour Cause

Flight Phase	Primary Cause (Most Reported Listed First)					
A300/A310/A300- 600	A319/A320/A321	A330/A340				
Ground	Electrical Equipment	APU Electrical Equipment	Electrical Equipment			
Takeoff	Engine Oil Leak	Engine Oil Leak Ingestion APU Oil Leak Leakage of rain repellent fluid	Engine (prior eng wash)			
Climb	Electrical Equipment De-icing Fluid Ingestion	Electrical Equipment APU Engine ECS Galley Equipment Leakage of rain repellent fluid	Green hydraulic overfill			
Cruise	Electrical Equipment	Electrical Equipment Galley Equipment Engine APU	Equipment Galley Equipment			
Descent	APU Oil Leak	APU Engine Electrical Equipment	Electrical Equipment ECS			
Approach	APU Oil Leak Galley Equipment	APU				

This section addresses oil contamination of the ECS. The possible sources of oil contamination of the air conditioning system is an oil leak from either the APU or an engine.

The majority of reports associated with oil contamination coincide with or closely follow one of the following crew actions: -

- Initiation of the APU bleed air supply
- Large change in power lever angle (PLA), i.e. top of descent, with engine bleed air already selected ON.

In these cases the air conditioning packs are subjected to changing bleed air inlet flow, pressure and/or temperature conditions. It should also be noted that the temperature of the APU bleed air supply can be higher than the engine air supplies. The generally higher APU air temperatures make it more likely that any existing contamination that is present within the air conditioning system will produce odours. Therefore, a report following initiation of the APU bleed air supply does not necessarily mean that the APU is the cause of the air conditioning contamination from which the smell can originate. Similarly, a smell report following a large change in engine power lever angle when APU AIR is OFF, does not necessarily mean that one or more of the engines is the cause.

In all instances of reported smells both the APU and engine bleed air supplies should be checked for evidence of contamination. Remember that the APU can contaminate both ECS packs, whereas for aircraft with 2 main engines; Engine 1 can only contaminate ECS Pack 1, and Engine 2 can only contaminate ECS Pack 2. For aircraft with 4 main engines Engines 1&2 can only contaminate ECS Pack 1, and Engines 3&4 can only contaminate ECS Pack 2. The process of determining the contamination source can be managed by use of a questionnaire as previously mentioned. Refer to EngOps-16316 for details of the ECS decontamination task which details where to look for oil contamination in the bleed system and ECS packs.

Post Event Maintenance

Diagnosing Continuing Problems

If the odour cause has not been confirmed and fixed, the use of the questionnaire shown in Attachment 1 will facilitate continued reporting if the operator chooses to return the aircraft to service. Attention is drawn to the importance of isolating the source by determining which pack and bleed configuration is involved

One possibility where the source of an oil leak/odour cannot be determined would be to operate the aircraft with each bleed supply OFF (in accordance with the MMEL requirements) in turn to identify a bleed configuration that confirms the odour. If this does not identify a bleed source of the odour, then operate using a single ECS pack to try and identify an ECS pack as a source of the odour. Note that a build-up of oil contamination within an ECS pack can occur over time and eventually cause the ECS pack itself to be the source of an odour. The reporting sheet at attachment 2 can be used to track the different ECS configurations and aid this process.

Aircraft Rectification

Following oil contamination of the aircraft bleed system and ECS, the system should be cleaned <u>following removal of the contamination</u> source, Ref EngOps-16316 and then maintained in a clean condition.

It may be prudent to replace the cabin air recirculation filters following significant in-service events where the filters have either become significantly contaminated, or remain odorous after the event. The recirculation filters may contain particulate residues that may help identify the cause of a cabin air quality incident. Note however, that the filters will not trap gaseous substances, only particulate matter.

Crew Medical Tests

Although it is very rare, an event involving physical symptoms being experienced by the crew requires a fast response in order to capture any available evidence that will confirm or discount any particular contamination source/scenario. Airbus has on occasion been asked to recommend what medical checks of affected crew are appropriate in such circumstances. Airbus does not make any recommendation about when or how crews should have medical checks, but advises that operators should seek medical advice about which medical checks would yield useful information after an event.

Note: In order to reduce the possibility of external variables influencing the results of such examinations, crew movement details between the flight and the medical examination should be recorded.

Record accurate and precise details of clinical symptoms: what symptoms were experienced? When during the flight did each symptom become apparent? How long did each symptom last? Was the symptom relieved by the use of oxygen? How were the onset of symptoms related to detected smell/odour? Were the symptoms related to any ECS system switch selections?

Contacts

Operators requiring more information or further advice should contact;

Nigel Dadswell

Environmental Control Systems, Customer Services Engineering

Phone 33 (0)5 62 11 87 58

Fax 33 (0)5 61 93 44 38

Email Nigel.Dadswell@Airbus.com

ATTACHMENTS

Attachment 1 - ECS Configurations

Part 1 – Isolating ENGINE/APU/PACK as the contaminant source

Notes	Pack 1	Pack 2	Engine Air	APU Air	Odour
	OFF	ON	ALL OFF	ON	YES/NO
	ON	OFF	ALL OFF	ON	YES/NO
	OFF	ON	ALL ON	OFF	YES/NO
	ON	OFF	ALL ON	OFF	YES/NO
Take-off config	ON	ON	ALL OFF	ON	YES/NO
Landing config	ON	ON	ALL OFF	ON	YES/NO
Landing config	ON	ON	ALL ON	OFF	YES/NO
	Take-off config Landing config Landing	OFF ON OFF ON Take-off config Landing config Landing CN	OFF ON ON OFF OFF ON ON OFF Take-off ON ON Config Landing ON ON Landing ON ON	OFF ON ALL ON OFF OFF ON ALL ON OFF OFF ON ALL ON ON OFF Config C	Notes Pack 1 Pack 2 Air Air OFF ON ALL ON OFF ON OFF ON ALL ON OFF ON OFF ALL ON OFF Take-off ON ON ALL ON OFF Landing ON ON ALL ON OFF Landing ON ON ALL ON OFF

contamination Source

Date	Notes	Engine Air #1	Engine Air #2	Engine* Air #3	Engine* Air #4	Odour
	APU Air OFF	OFF	ON	ON	ON	YES/NO
	APU Air OFF	ON	OFF	ON	ON	YES/NO
	APU Air OFF	ON	ON	OFF	ON	YES/NO
	APU Air OFF	ON	ON	ON	OFF	YES/NO

• A330/A340/A380 only

ATTACHMENT 2 - CABIN AIR CONTAMINATION REPORTING SHEET

	ATT	racular.	NT 2 - 64	STAL AT	D CONTA	BATRIA.	TON	rnor	Princ c		-	9
			NT 2 - CA									
ontamination is de ne normal behavior iscomfort associate abin/Flight Crew in ttach additional in rouble shooting ass	ur of the ed with nput as formati	e aircra the cor necession/com	ft or disturtamination of the control of the contro	on. Plea that the applical	crew and se comple e first sec ble or not	or pa lete thi zion, p cover	ssenge is form olus ite ed by 1	ers. The with I says ma this for	ere may Mainten arked wi rm. Data	or n iance ith a irec	nay not be e, Enginee (*) are no eived will	e physica ering and ecessary. be used
A/C Reg	A/C To		From	J GIE CA	To	$\overline{}$	Date	/ Even	LS USUSL	\neg	AT (°C)	NIGIVS151
Eng Start Method			Time to 5	Start		1	Eng Sta	rt Atte	mpts			
Departure Time Arrival Time Ext Time Fit Lvl IFTB Delay mn										mn		
Gnd - Ph 1 Gnd	- Pax B	oarded	Taxi Out	T/O	Climi	,	Cruise	Des	cent .	Appn	pach Tax	xi In
□ □ □ □ Top?□ □												
*Mark posn, of Odour/Visual Contamination(C) +Toilers&Galleys (G, T): Mark posn, of surrounding vehicles/ a/c:												
BLD #1 ON	Packi f		Love	T (fort.			ind				
SLD #2 ON	Pack1 F Pack2 f			CKPT Temp (°C): FWD CAB Temp(°C):			Dire	ction	Fwd	_	Port	and 🗆
BLD #3 ON	COT1(°		MID	CAB Ter	no(°C):		fron	n?	ALL	+	3(8) 00	a.o.C.
BLD #4 ON	COT2(°			CAB Ten			Attac					
APU BLD ON		NS ON F	_	ice on B	11 1	1		Repor	t irints as		Attach ca	
Bleed Config at Ta		in on [-	ECAM M				opriate				
DIEEU COIRING OC 12	Keurr		Paty	CUMPI PE	sys :					1_		
LAV smoke wit	1g 🔲	CRG sm	oke wrng [Avr	cs smoke	wing [out before	
Eng Pwr *Odoun/Visible		mination l	Description	.,,	rsers Used Sonal Info		2. 3. 4. 5. 6. 7.	Unsc APU De-Id	Maintena heduled Service cing Repellen	nce Main		
Physiological S	miptom	s .	Passenger	Ca	bin Crew	Flight	Crew		i, please ew statio		ribe (incl. 9	ieat No
None Headache Dizziness/F Nausea/Vo Eye/Nose I Other (see	miting rritation	e)] [] []		or ch	ew statio	19.7g.5		
What do YOU				Andrew Control	5.77 M		1.		-1 -	. 1.		1 - 4 1
Ground Eqpmt	-	+	gine	De-Icin	g Galle;	Eqpm	-	argo	Electric	al I	ECS Packs	-
Ret	mm to S		h ? 🗌	61 0344	I38 a.moil	- pinal		Mairh	EKS-COM O	E SIGN	tr local Aid	here RCSN
Eviets	medel (FeF teFe							ange on the		you	a areas resi	الله بالله حدد
		AIRB	US PF.	TSE ARI	ICLE Eng	Ops-10	1325					

Additional Note

THIS ARTICLE REPLACES SIL 21-132

Please also note that

- SIL 21-029 is replaced by EngOps16316
- SIL 21-050 is replaced by EngOps16317
- SIL 00-081 is replaced by EngOps16326